

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2 5 5 0	DATE	June. 10. 2010
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>Due to the inappropriate polishing condition of the circuit board for combination switch with turn signal lamp switch, it has a rough surface. Therefore worn-out dust which occurred by the switch operating may accumulate on the contact point. If turn signal lamp is switched on, this can result in prevent current from the contact point and the turn signal lamp may not be turned on.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-V36	S K Y L I N E	2 0 0 6	1 2, 0 6 3
DBA-NV36		~	1, 9 8 9
DBA-PV36		2 0 0 7	4, 6 6 1
		TOTAL	1 8, 7 1 3