

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2551	DATE	June 10, 2010.
MANUFACTURER	YANMAR CONSTRUCTION EQUIPMENT CO. , LTD.		
DESCRIPTION OF DEFECT	Because fixing screws of a door window glass might be tightened with insufficient torque and the spring hinge might be bent improperly at production process, the fixing bolts might loosen and/or the spring hinge might be damaged due to the vibration of the cabin during operation. At worst, the window glass would drop from the cabin.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
EDM-V36	V3-6	2009	188
EDM-V46	V4-6	2009	81
EDM-V51	V5-1	2009	42
EDM-RW05	LK40Z-5	2009	61
EDM-RX05	LK50Z-5	2009	76
		TOTAL	448