VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	2552	DATE	June 10, 2010.	
MANUFACTURER	YANMAR CONSTI	RUCTION EQUIPMENT CO.,	LTD.	
DESCRIPTION OF DEFECT	A retaining ring might be installed improperly on a drive shaft of hydraulic pump come off at operation. The drive shaft could slide out of the correct position after retaining ring coming off. As a result, oil leaks from the hydraulic pump, because the sealing surface on the shaft would detach from a oil seal. At worst, the machine can not travel at all.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
L2DA	V2-3B	2009	6
EDM-V36	V3-6	2009	25
EDM-V46	V4-6	2009	14
EDM-V51	V5-1	2009	7
EDM-RW05	LK40Z-5	2009	4
EDM-RX05	LK50Z-5	2009	1
		TOTAL	57