

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2556	DATE	JUN. 15 2010
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	Regarding the service parts for air compressor, some faulty crankshafts were supplied. If this faulty crankshaft is used, insufficient lubrication of the air compressor will occur. This may lead to engine stall in the worst case, and the engine will not be restarted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
U-MJ628F	FUSO AERO MIDI	1995	1
U-MK517J		1993	1
U-MK626J		1994	1
		TOTAL	3