

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2557	DATE	Jun. 17, 2010
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	On certain flat cables of the steering roll connectors, chemical stress crack may occur on the cable surface due to manufacturing dispersion in grease which is applied to the cable during assembling process of connectors. Under these circumstances, origin of the crack in flat cable may develop to breakage of the lead wire if it was continuously used, which will possibly result in inoperative driver side air bag and no sounding of horn.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-BM9	Legacy	2009~2010	7,449
DBA-BR9		2009~2010	19,019
DBA-BRF		2009~2010	865
		TOTAL	27,333