

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2559	DATE	June 17 . 2010
MANUFACTURER	Komatsu Utility Co. , Ltd.		
DESCRIPTION OF DEFECT	Valve adjust screw has a heat treatment failure. This defective screw has been already assembled in our engines. It is possible that the screw should be worn in a short time leading to an excess emission level over the regulation standard if users leave the defect without repair.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-WA106A	WA30-6	2009	3
EDM-WA107A	WA40-6,WA50-6	2009	11
		TOTAL	14