

VEHICLES SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2543	DATE	June 17, 2010
MANUFACTURER	YANMAR CO., LTD.		
DESCRIPTION OF DEFECT	Valve adjust screw has a heat treatment failure. This defective screw has been already assembled in the engines. It is possible that the screw should be worn in a short time leading to an excess emission level over the regulation standard if users leave the defect without repair.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-30K	CT226	2009	3
	CT230	2009	2
24J	EG220	2009	5
EDM-24J	EG222	2009	3
	EG224	2009	1
	EG224X	2009	4
EDM-30J	EG227	2009	4
	EG227X	2009	1
	EG230X	2009	1
EDM-34FF	EF334V	2009	1
SB-80C	CT801	2009	1
EDM-45K	CT401	2009	2
	CT451	2009	5
EDM-45L	EG437Y	2009	33
	EG441Y	2009	23
	EG445Y	2009	24
KDN-53H	EG53	2009	3
KDN-53J	EG53Y	2009	2
EDN-65J	EG58Y	2009	2
	EG65Y	2009	10
KDP-83B	EG83Y	2009	4
-	GC338V	2009	7
-	GC441V	2009	15
-	GC447V	2009	11
-	GC698	2009	1
		TOTAL	168