

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2519	DATE	June 17 2010
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	The clamp added to the hose of the torque converter by campaign no. 2024 may be broken due to poor strength of the clamp. Accordingly, when you use machine for some period, the hose of the torque converter may contact with the pipe, be worn and have a hole which cause oil leakage, then you may fail to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SD-KRC002	KR-65H	2005 ~ 2006	170
		2006 ~ 2008	364
		TOTAL	534