VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	2560	DATA	June.	18. 2010
MANUFACTURER	Nichijo Manufacturing Co.,Ltd.			
DESCRIPTION OF DEFECT	For lack of lubrication of the joints for hydraulic pump axis Rotary Snowplow power transmission equipment (gearbox) in during use, wear the joints have to be. Therefore, you might can no longer be driving and continue to use in its entirety, for hydraulic pump axial joints is worn away.			
ТҮРЕ	COMMERCIAL NAME	MODEL YEA RECALLED		NUMBER OF VEHICLE
R 0 8 C	HTR145	2009		1
EDR-R08C	HTR145	2008~20	0 1 0	1 4
R 0 9 C	KBR103	2009		1
EDR-R09C	KBR103	2008~20	0 1 0	2 5
R 1 0 C	HTR85	2010		1
KDP-R10C	HTR85	2009~20	0 1 0	8
		TO	OTAL	5 0