## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	2568	DATE	Jun.30.2010	
MANUFACTURER	ТОУОТА			
DESCRIPTION OF DEFECT	In the airbag system of the subject vehicles, due to improper assembly of the airbag inflator, which is used in the passenger side front airbag, some inflators were produced with an insufficient amount of gas generators. In this condition, gas generators in the inflator may become broken and powdered by vehicle vibration over time. This can create abnormal pressure in the inflator body during airbag activation, causing it to break and scatter. This increases the risk of personal injury during airbag inflation.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TA-NZE120	COROLLA	2000	228
		2000-2001	1,049
TA-NZE121 TA-NZE121G	COROLLA COROLLA FIELDER	2000-2001	8,417
	COROLLA RUNX	2000-2001	11,454
TA-NZE124 TA-NZE124G	COROLLA FIELDER	2000	1,341
		2000	1,294
TA-ZZE122 TA-ZZE122G	COROLLA COROLLA FIELDER	2000	6,156
		2000	2,839

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TA-ZZE123G	COROLLA FIELDER	2000	1,233
TA-ZZE124 TA-ZZE124G	COROLLA COROLLA FIELDER	2000	1,396
171-222124G	COROLLATILLELA	2000	410
KE-CE121 KE-CE121G		2000	150
RE-CE1210		2000-2001	172
TA-ACM10G	GAIA	2001	20
KH-CXM10G		2001	1
GF-SXM15G		2001	4
TA-ACM21W	IPSUM	2001	44
		2001	5
TA-ACM26W		2001	6
		2001	1
TA-JCG10	BREVIS	2001	39
TA-JCG11		2001	15
TA-GX110	MARK	2000-2001	1,180
		2000-2001	4,159
TA-GX115		2000-2001	140
		2000	654

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-JZX110	MARK	2000-2001	1,860
TA-JZX110		2000-2001	5,997
TA-JZX115		2000-2001	120
		2000	354
		TOTAL	50,738