

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2569	DATE	Jun.30.2010
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	Due to an inadequate process for assembling the seat belt buckle of the front inner seat belt for the subject vehicles, a component inside the buckle may be damaged. In this condition, if the broken piece of the component gets stuck inside the buckle, a passenger may not be able to buckle the seat belt.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-URJ202W	LAND CRUISER	2010	32
		2010	49
DBA-AZE154H	BLADE	2010	7
DBA-AZE156H		2010	7
DBA-GRE156H		2010	4
DBA-AZE154H DBA-AZE156H DBA-GRE156H		Vehicles in which the subject service part is installed	2
		TOTAL	101