

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2567	DATE	June. 30. 2010
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	For the front passenger's airbag, its inflator may be underfilled with gas generating propellant due to inappropriate work procedure. Gas generating propellant so filled may be reduced to powder by vehicle vibrations and can, if and when the airbag inflates, cause abnormal rise in inflator internal pressure by which the container can be broken and component parts could be thrown out, causing injury to the passenger.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-RN1	STREAM	2000~2001	7,281
		2001~2002	21
LA-RN2		2000~2001	1,359
		2002	1
LA-RN3		2000~2001	9,352
		2002	69
		2002	2
LA-RN4		2001	18
		2002	1
LA-ES1		CIVIC FERIO	2000
LA-ES2	2000		650
LA-ES3	2000		718
LA-GD1	FIT	2001	53
LA-GD2		2001	14
		TOTAL	24,522