## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2575	2575 DATI		July 9. 2010	
MANUFACTURER	Komatsu Utility Co. , Ltd.				
DESCRIPTION OF DEFECT	Due to improper routing of the harness of the travel and load interlock function, which prohibit driving and cargo handling operation without a driver seated in the seat, rainwater might infiltrate into the connectors of the harness. Therefore if a machine is continuously used under such condition, the interlock function might malfunction due to the defective energizing, and in the worst case a machine can not travel.				
TYPE	COMMER( NAM		MODEL YEAR RECALLED		NUMBER OF VEHICLE
EDR-M246	FD100,FD1	15,FD120	2008~2009		9
EDR-M247	FD135,FD15	DE,FD160E		3~2010	18
			Τ(	OTAL	27