VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2 5 7 4	DATE	Jul 15 ,2010
MANUFACTURER	TCM CORPORATION		
DESCRIPTION OF DEFECT	There is a case to interfere Alternator swiring with a hydraulic pressure hose in the neighborhood depending on installed method. Therefore, coating of the wiring burst and wire blade of the hose is bared in touch of this state when using it continuously so a fire might occur to make a short-circuited in worse case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
F 1 0 6	F D 3 5 T 9 F D 3 5 C 9 F D 4 0 T 9	2 0 0 3 ~ 2 0 0 4	7 6
SB-F106	F D 4 0 C 9 F D 4 5 T 9 F D 4 5 C 9	2 0 0 4 ~ 2 0 1 0	4 1 3
F 1 0 7	F D 5 0 T 9	2 0 0 4	1 1
SB-F107	F D D O 1 9	2 0 0 4 ~ 2 0 1 0	8 3
		TOTAL	5 8 3