

## VEHICLES SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	2576	DATE	July 22. 2010
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	Among the steering mechanism, the steering rod end and the steering cylinder rod is improperly welded. During the operation of the steering handle, there is a concern that the welding between the steering rod end and the steering cylinder rod will break and then finally the tractor cannot be operable.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
—	GK-13 GK-14 GK-16 GK-18	2010	61
			TOTAL 61