

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2 5 8 8	DATE	Jul. 27.2010
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>Due to an insufficiency the durability of the hazard switch on the vehicles were equipped the side turn lamps, the contact point of the hazard switch may wear excessively by the turning on the electricity when the switch is operated. In an extreme case, the hazard warning signal flasher may be inoperative even though the hazard switch is turned on.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
KK-BJW41	NISSAN CIVILIAN	2 0 0 6	1
		TOTAL	1