

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2 5 8 9	DATE	August.25.2010
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	Due to insufficient welding of the direction indicator lamp, cracks of the lamp lens might be made at the welding section and water influx of the lamp might occur. This defect causes non-conduction of the bulbs, and the bulbs might not lighten in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-CD2 series	—	2009~2010	21
ADG-CD4 series PKG-CD4 series	—	2009~2010	799
ADG-CF4 series	—	2009~2010	14
ADG-CG2 series	—	2009~2010	18
ADG-CG4 series PKG-CG4 series	—	2009~2010	550
ADG-CK2 series	—	2009~2010	26
ADG-CV2 series	—	2009~2010	213
ADG-CV4 series PKG-CV4 series	—	2009~2010	90
ADG-CW2 series	—	2009~2010	43
ADG-CW4 series PKG-CW4 series	—	2009~2010	431
ADG-CX2 series	—	2009~2010	6
PKG-CX4 series ADG-CX4 series	—	2009~2010	30
ADG-CZ4 series	—	2009~2010	38
ADG-GK4 series PKG-GK4 series	—	2009~2010	514
ADG-GW4 series	—	2009~2010	96
BDG-LK36 series	Condor	2009~2010	43
BDG-LK37 series	Condor	2009~2010	36
BDG-MK35 series	Condor	2009~2010	64
BDG-MK36 series	Condor	2009~2010	478

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-MK37 series	Condor	2009~2010	216
BDG-PK36 series	Condor	2009~2010	46
BDG-PK37 series	Condor	2009~2010	196
BDG-PW37 series	Condor	2009~2010	102
ADG-SF4 series	—	2009~2010	3
ADG-SZ4 series	—	2009~2010	17
ADG-HF4 series	—	2009~2010	3
ADG-HZ4 series	—	2009~2010	3
		TOTAL	4,096