VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2598	DATE	Aug. 27, 2010	
MANUFACTURER	DAIHATSU			
DESCRIPTION OF DEFECT	On a hybrid motor, it is possible that excessive load might be applied to the bearing due to dimensional dispersion occurred in the manufacturing process, which is caused by improper control of the processing machine. Grease applied to the bearing affected may be deteriorated due to heat of the bearing when it is working. Accordingly, if a vehicle with this condition is used continuously, it could possibly result in engine cutting out.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LE-S320V	HIJET	2005-2010	402
HAD-S320V	LIJEI		
		TOTAL	402