

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN NO.	2 5 9 2	DATE	AUGUST,27,2010
MANUFACTURER	MITSUBISHI AGRICULTURAL MACHINERY CO.LTD.		
DESCRIPTION OF DEFECT	Fan belt adjustment arm may be damaged due to the vibration by the high idling of the engine. If the fan belt adjustment arm is continued to use under the damaged condition, this may cause overheating.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDN-VC63A	VY463	2008 ~ 2010	48
	VG563		50
		TOTAL	98