

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2594	DATE	August 31 ,2010
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		Since some outer handle brackets on the emergency door were improperly welded, the welded area of the bracket could be damaged and in the worst case the emergency door could not be opened.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-LV234L1	ERGA	2005-2007	440
PKG-LV234L2 PDG-LV234L2		2007-2008	13
PJ-LV234N1		2005-2007	221
PKG-LV234N2		2007	1
KL-LV280L1		2005	4
		TOTAL	679