

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2596	DATE	Aug.31 2010
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some large-sized intercity express buses, improper application of the sealant to the through-holes for the rearview mirror heater harness on the left and right pillars may cause ingress of water through the holes during driving in rain and washing. If the bus continues to be used in this condition, faulty operation of some electrical component may occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-MU66JS	FUSO AERO KING	2008~2010	38
		TOTAL	38