

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2587	DATE	Aug.3 2010
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some rear tandem-axle heavy-duty trucks, the axle housing for rear-rear axle (driven axle) has defect due to its improper welding. This may cause cracks in its welding section. If the truck continues to be used in this condition, the axle housing will break in the worst case, which will lead to overheated brakes or tire-to-frame contact, and finally resulting in a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL-FU50JNY KAI	FUSO	2001~2002	6
KL-FU50JSY KAI		2000	1
KL-FU50JTZ		2000~2002	130
KL-FU50JTZ KAI		2001	1
KL-FU50JUZ		2000~2002	403
KL-FU50JUZ KAI		2001~2002	6
KL-FU50KTZ		2000~2001	12
KL-FU50MTZ		2000~2002	27
KL-FU50MUZ		2000~2002	125
KL-FU50MUZ KAI		2001	1
KL-FU54JTZ		2000~2002	63
KL-FU54JUY		2000~2002	156
KL-FU54JUZ		2000~2002	1,226
KL-FU54JYZ		2001~2002	61
KL-FU54MUZ		2000~2002	38
KL-FU55JUZ		2000~2002	197
KL-FU55JYZ		2001~2002	19
		TOTAL	2,472