

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(~~Domestic~~) Import Vehicles

CAMPAIGN No.	2599	DATE	September 3, 2010
MANUFACTURER	KCM Corporation		
DESCRIPTION OF DEFECT	There was a potential that the harness for the head lamps, turn signals, and/or width lamps may be strained when the machine turns due to their inadequate wiring arrangement. This could result in disconnected wiring after some period of operation; the lamps would not work.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-70C5	70ZV-2	2007-2010	111
JDS-RE07	LK230-6		10
		TOTAL	121