

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	2 6 0 0	DATE	September 10,2010
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p>Due to improper manufacturing process of accelerator pedal angle sensor, which is applied in an accelerator pedal, mounting bolts tightening torque may be insufficient.</p> <p>Therefore if a machine is continuously used, dropout of accelerator pedal angle sensor may happen, and engine rpm might not increase when accelerator pedal is treadle in the worst case.</p> <p>Due to improper manufacturing process of accelerator pedal sensor harness clamp, which is applied in an accelerator pedal, mounting bolts tightening torque may be insufficient.</p> <p>Therefore if a machine continuously used, damage of accelerator pedal sensor harness may happen, and engine rpm might not change from low idle in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-WA105	WA200-6	2007 ~ 2010	133
EDR-WA103	WA270-6	2007 ~ 2010	84
EDR-WA108	WA320-6	2007 ~ 2010	68
JDS-WA095	WA380-6	2006 ~ 2010	46
JDS-WA091	WA430-6	2006 ~ 2010	21
JDS-WA098	WA470-6	2006 ~ 2010	7
	WA480-6	2006 ~ 2010	3
JDS-WA096	WA500-6	2006 ~ 2010	2
JDS-GD024	GD755-5	2008 ~ 2010	21
	GH320-5	2008 ~ 2010	10
TOTAL			395