

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2606	DATE	September 16, 2010
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Securing Bolts of the Control Arm onto vehicle body may be not strong enough, as the incorrect material was found used in the production process of the bolt. If the two securing bolts are tightened by the higher torque during maintenance service, the bolts may be broken and the control arm comes out from the connecting part with vehicle body. Then, it may be hard for the customer to continue the vehicle driving.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ME34S	MW	2010	9
ABA-ME34S		2010	2
		TOTAL	11