

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2 6 0 9	DATE	September 16, 2010
MANUFACTURER	ISEKI & CO., LTD.		
DESCRIPTION OF DEFECT	A defective welding of the boss of the cylinder plate has been found out. Therefore, unless the defective part is replaced, there is a possibility that the steering system could not work correctly.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
T129F	JKA17	2008—2010	8
T133F	JKA17D	2008—2010	83
	HV17	2008—2010	23
T136F	JKA19D	2008—2010	86
	HV19	2008—2010	17
T148F	JKA21S	2008—2010	319
	HV21	2008—2010	50
TOTAL			586