VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2602	DATE	Sep.17 2010	
MANUFACTURER	TCM CORPORATION			
DESCRIPTION OF DEFECT	Due to improper wiring route for the battery cable into the starter motor, both (+) and (-) terminal of its battery cable may be broken by trembling the engine on operation. In the worse case, the engine starting is impossible.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
S A - F 1 3 4	F D 1 0 T 1 3 F D 1 0 C 1 3 F D 1 5 T 1 3	2005~2008	3 6
E D M - F 1 3 4	F D 1 5 C 1 3 F D 1 8 T 1 3 F D 1 8 C 1 3	2008~2010	3 9
		TOTAL	7 5