

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2 6 1 1	DATE	S e p . 2 1 . 2 0 1 0
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In the manufacturing process of a connector section of which connector to hook up to the Engine Control Unit (ECU), some waterproof seals inside the connectors were damaged. Because of the damage, water got inside the connector while washing the vehicle, etc., a leak current was generated causing the ECU to falsely recognize it. In the worst case scenario, the engine will stop and will not start again. Or, the speedometer may possibly give erroneous indication.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
E B L - V H 0 2 J	XVS400 DRAGSTAR	2 0 0 9 ~ 2 0 1 0	5 8 0
	XVS400C DRAGSTAR CLASSIC	2 0 0 9 ~ 2 0 1 0	8 2 0
		TOTAL	1 , 4 0 0