

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2608	DATE	Sep. 28 2010
MANUFACTURE	MARUYAMA MFG.CO.,INC		
DESCRIPTION OF DEFECT	A part which is connected steering gearbox has not enough strength, and it may be cracked on welding part. If continue to be used on that condition, the part will be broken and the vehicle can not be steered finally.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
MARUYAMA	MARUYAMA STEREO SPRAYER SSA-G535	2009 ~ 2010	63
		TOTAL	63