

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN NO.	2 6 1 9	DATE	8 th .Oct.2010
MANUFACTURER	TCM CORPORATION		
DESCRIPTION OF DEFECT	With management deficiency of the production facility, it causes to create with the stopper bolt's position is inappropriate to limit steering tires in steerable range not to play a role as the stopper bolt that the rear tires do not stop at correct position when full turning which may reach damaging the tires by interfering with the steering axle in worse case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
S B - S 5 5	S D 2 3 T 8 S D 2 5 T 8	2 0 1 0	5
		TOTAL	5