VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2618	DATE	Oct.12 2010			
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation					
DESCRIPTION OF DEFECT	On some large-size route buses, the construction of the vehicle speed sensor mounted on the automatic transmission is improper. The wiring in the sensor may break, and if this occurs, the speed will no longer be indicated on the speedometer nor be recorded by the tachograph.					

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
KL-MP35JK	FUSO AERO STAR	2001~2003		4
KL-MP35JM		2003~2005		6
KL-MP35JM KAI		2000~2001		13
KL-MP35JP		2003~2005		21
KL-MP37JK		2001~2004		22
KL-MP37JK KAI		2003~2007		69
KL-MP37JM		2003~2005		8
KL-MP37JM KAI	I		03~2007	45
	•	•	TOTAL	188