

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2620	DATE	Oct.14.2010
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain trucks and buses with full air brake system, due to inadequate heat-treatment, the roller contact surface of the tappet in the wedge and roller assembly of the wheel cylinder could be worn and dented at the early stage. This can cause the wedge and roller assembly function inaccurately resulting in a decrease of braking force.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-FH1AGXA	Hino Profia	2009	2
BDG-FH1AHXA		2009	1
BDG-FH1ALXA		2009	4
BDG-FH1ANXA		2009	1
BDG-FH1ARXA		2009	1
BKG-FN1AWXA		2009	15
BKG-FN1AWXG		2009	4
BDG-FN1EWXG		2009	1
BDG-FQ1EWYG		2009	7
BDG-FQ1EWYJ		2009	1
BDG-FR1AKXA		2009	1
BKG-FR1ANXA		2009	1
BDG-FR1APYA		2009	18
BKG-FR1APYA			
BKG-FR1APYG			
BDG-FR1AXYA		2009	4
BDG-FR1AXYG			
BKG-FR1AXYG			
BDG-FR1EPYA		2009	5
BDG-FR1ESYA		2009	1
BDG-FR1EUYA		2009	1
BDG-FR1EXYA		2009	80
BDG-FR1EXYG			
BKG-FR1EXYG			
BDG-FR1EXYJ			
BKG-FR1EXYJ			
BDG-FR1EZYG		2009	34
BKG-FR1EZYG			
BKG-FR1EZYJ			
BDG-FS1AKXA		2009	6
BDG-FS1EKXA		2009	17
BDG-FS1EPYA		2009	6
BDG-FS1ERYA		2009	7
BDG-FS1EWYA		2009	17
BDG-FS1EWYG			
BKG-FS1EWYG			
BDG-FS1EWYJ			
BDG-FS1EZYA		2009	3
BDG-FS1EZYG			
BDG-GN1AMXA		2009	1

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-GN1APYA	Hino Profia	2009	23
BDG-GN1APYG		2009	33
BDG-SH1EDXG		2009	2
BKG-SH1EDXG		2009	1
BDG-SH1EDXJ		2009	5
BDG-SH1EFXG		2009	4
BDG-SH1EGXG		2009	1
BDG-SS1EKXA		2009	2
BDG-FG8JGWA	Hino Ranger	2009	3
BDG-FG8JJWA		2009	2
BDG-FG8JKWA		2009	8
BDG-FG8JMWA		2009	2
BDG-FG8JPWA		2009	3
BDG-GK8JKWA		2009	2
BDG-GK8JLWA		2009	3
BDG-GK8JRWA		2009	1
BDG-GK8JWWA		2009	2
BDG-GK8JWXA		TOTAL	379
BJG-RU1ASAR	Hino SELEGA	2009	2
PKG-RU1ESAA		2009	41
BDG-RU8JHAA		2009	5