

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2621	DATE	October 14 ,2010
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On certain buses with full air brake system, due to inadequate heat-treatment, the roller contact surface of the tappet in the wedge and roller assembly of the wheel cylinder could be worn and dented at the early stage. This can cause the wedge and roller assembly function inaccurately resulting in a decrease of braking force.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PKG-RU1ESAJ	ISUZU GALA	2009	26
BDG-RU8JHAJ		2009	2
		TOTAL	28