## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	2623	DATE	October	15	,2010
MANUFACTURE	HITACHI CONSTRUCTION MACHINERY CO., LTD				
DESCRIPTION OF DEFECT	Due to improper control program of the HST pump and motor, if it is sifted very busy, rapid and repeat to forward and reverse that the bearings in HST pump will be failed early.  If the machine is used by such condition, in case of worst there is potential the machine will be not able to run.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
EDR-HS61	ZW140	2007 - 2009	42	
EDR-HS61L	211110	2007 2000		
EDR-HS62	ZW150	2008 - 2009	6	
EDR-HS62L				
EDR-S61	ZW140	2007 - 2010	87	
EDR-S61F		2007 2010		
EDR-S62	ZW150	2008 - 2010	25	
EDR-S62F	2100	233 2310		
		TOTAL	160	