VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2636	DATE	October. 21. 2010
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	For the brake master cylinder, performance evaluations were inadequate with regard to lubricity with commercially available brake fluids. Therefore, use of brake fluid with low polymer content may, even if it is the brake fluid meeting the standards, result in poor lubrication of the rubber seal at the rear edge of the cylinder, and the seal may thereby be upturned. In such a case, brake fluid will leak through that portion of the seal, causing the brake warning light to go on. Continued use in this condition can, in the worst case, result in loss of the brakes' effectiveness.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-KB1	LEGEND	2004~2005	931
		2005~2006	2,381
		2006~2007	658
		TOTAL	3,970