

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2626	DATE	Oct.21.2010
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	Due to the improper control program for illumination of the combination meter (e.g. the speed meter), the combination meter light may not illuminate when the front position lamp is turned on by the operation of the light switch.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ZRR70G DBA-ZRR70W	VOXY NOAH	2010	1,333
DBA-ZRR75G DBA-ZRR75W		2010	536
		TOTAL	1,869