

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2622	DATE	October 21, 2010
MANUFACTURER	Kobelco Cranes Co., Ltd		
DESCRIPTION OF DEFECT	<ol style="list-style-type: none">1. Due to the inappropriate structure of the flexible tube of the exhaust pipe, the motor vibrations may create cracks on that component, and in worst case, the exhaust leak from such cracks may cause burning of the nearby electric wirings.2. Due to the inappropriate position of the piping clamp in the hydraulic piping for the front wheels of the transmission system, the hydraulic pulses may create cracks on that piping, and in worst case, the hydraulic oil may leak from the cracks and disable further traveling of the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEARS RECALLED	NUMBER OF VEHICLE
JDS-EE02	RK250-7	2008 - 2010	201
		TOTAL	201