

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2629	DATE	Oct. 22, 2010
MANUFACTURER	SHO-SHIN Co, Ltd.		
DESCRIPTION OF DEFECT	In the fuel apparatus of a crop-dusting vehicle when a fuel tube laid pipes to injection nozzle from a hollow screw for pulling out fuel-air of the injection pump in power engine interferes in an accelerator wire link base and the vehicle is operated continuously in the state as is, the fuel tube concerned is damaged, and the fuel leaks, and in the worst case, it might cause fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-F0	3S-VE1050C	2009-2010	26
		2010-2010	15
TOTAL			41