

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2 6 3 5	DATE	Oct.28.2010
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Due to inappropriate operations at the manufacturing process of the diode in power supply relay for engine control, an irregular contact can be made at a terminal in a relay. If the vehicle continues to be driven in this condition, the engine may not start or the engine may stall during a driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-E11	NOTE	2 0 0 3 ~ 2 0 0 6	103, 528
DBA-NE11			13, 371
DBA-C11	T I I D A		79, 298
DBA-NC11			10, 182
CBA-JC11 DBA-JC11			8, 124
DBA-SC11			39, 613
DBA-SNC11	T I I D A L A T I O		4, 871
CBA-SJC11 DBA-SJC11			4, 490
UA-BZ11 CBA-BZ11 DBA-BZ11			124, 494
UA-BNZ11 CBA-BNZ11 DBA-BNZ11	C U B E		18, 269
DBA-YZ11			12, 883
UA-BGZ11 CBA-BGZ11 DBA-BGZ11			49, 680
DBA-YGZ11			6, 167
DBA-YGNZ11			986

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
UA-AK12 CBA-AK12 DBA-AK12	MARCH	2 0 0 3 ~ 2 0 0 6	134, 496
UA-BNK12 CBA-BNK12 DBA-BNK12			14, 256
UA-BK12 CBA-BK12			9, 604
DBA-YK12			304
CBA-C25 DBA-C25	SERENA		82, 977
CBA-NC25 DBA-NC25			15, 741
DBA-CC25			4, 836
CBA-B30 DBA-B30	LAFESTA		46, 760
CBA-NB30 DBA-NB30			7, 789
DBA-Y12	WINGROAD		15, 141
DBA-NY12			3, 102
DBA-JY12			4, 064
DBA-KG11	BLUEBIRD SYLPHY		15, 385
DBA-G11			3, 101
DBA-NG11			1, 247
		TOTAL	834, 759