

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	2 6 4 0	DATE	October.28.2010
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	Due to inappropriate frame assembly around the front axle, the right side tire touches the drag link when turning the steering to far left with winter tires. This defect causes rusting on the surface of drag link, and the link might be broken in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KK-RM252 series	—	1999~2007	305
KL-JP252 series	—	1999~2005	444
		TOTAL	749