

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2641	DATE	November 4 ,2010
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	The tail lamp, the front fog lamp and the side back lamp had electric circuits inadequately arranged, so big current flowed through the tail lamp relay, causing the relay contact to produce heat. Thus, the plastic portion and the connector of the parts were deformed. If they are used as are, this may cause a contact failure, so that the tail lamp and so on may not be lighted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL-LT233J2	ERGA	2000-2005	191
KL-LT333J2		2000-2004	54
PJ-LV234L1		2004-2007	1,217
PJ-LV234N1		2004-2007	642
PJ-LV234Q1		2005-2007	103
KL-LV280L1		2000-2005	1,173
KL-LV280N1		2000-2005	623
KL-LV280Q1		2000-2005	163
KL-LV380L1		2000-2001	18
KL-LV380N1		2000	5
KL-LV834L1		2000-2005	234
KL-LV834N1		2000-2004	65
KK-LR233E1		ERGA MIO	1999-2001
KK-LR233F1	1999-2004		192
KK-LR233J1	1999-2004		1,506
PA-LR234J1	2004-2007		722
KK-LR333E1	2001		2
KK-LR333F1	2001		1
KK-LR333J1	1999-2004		74

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL-KV280L1	HINO BLUE RIBBON II	2004-2005	41
KL-KV280N1		2004	4
PA-KR234J1	HINO RAINBOW II	2004-2007	255
		TOTAL	7,390