

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2643	DATE	November 4 ,2010
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	In the rear door to which the jam protection systems (the door edge switch) was installed, the door wiring installation position was inadequate, so some wiring rubbed against the door engine rod. Thus, if it is used as is, the wiring will be disconnected. In the worst case, the door may not be closed, thereby rendering the vehicle inoperative.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-LV234L1	ERGA	2004-2006	497
PJ-LV234N1		2004-2006	174
KL-LV280L1		2000-2005	517
KL-LV280N1		2001-2005	136
KL-LV834L1		2000-2005	188
KL-LV834N1		2000-2004	28
PA-LR234J1		ERGA MIO	2004-2006
KL-KV280L1	HINO BLUE RIBBON II	2004-2005	39
		TOTAL	1,771