

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2642	DATE	Nov.4.2010
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	The tail lamp, the front fog lamp and the side back lamp had electric circuits inadequately arranged, so big current flowed through the tail lamp relay, causing the relay contact to produce heat. Thus, the plastic portion and the connector of the parts were deformed. If they are used as are, this may cause a contact failure, so that the tail lamp and so on may not be lighted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-KV234L1	Hino Blue Ribbon II	2004~2007	591
PJ-KV234N1		2005~2007	543
PJ-KV234Q1		2005~2007	213
PJ-KV234Q1(KAI)			
		TOTAL	1,347