

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2644	DATE	Nov.4.2010
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	In the rear door to which the jam protection systems (the door edge switch) was installed, the door wiring installation position was inadequate, so some wiring rubbed against the door engine rod. Thus, if it is used as is, the wiring will be disconnected. In the worst case, the door may not be closed, thereby rendering the vehicle inoperative.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-KV234L1	Hino Blue Ribbon II	2004~2006	336
PJ-KV234N1		2005~2006	41
		TOTAL	377