

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2646	DATE	Nov. 4, 2010
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	Due to the improper program of the Electric Power Steering control computer, if the vehicle is driven at high speed on the patterned indented road surface which warns of the swerve from the traffic lane, vibration from the road surface may be incorrectly recognized, causing the power steering function to become inoperative, which could result in an increase of the steering force.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-M600S	BOON	2010	1,365
DBA-M601S			222
DBA-M610S			614
		TOTAL	2,201