VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2647	DATE	November 9. 2010	
MANUFACTURER	Komatsu Utility Co. , Ltd.			
DESCRIPTION OF DEFECT	1.Because acceleration sensor of pedal against statistical electricity, when statistical electricity is charged, sensor does not work correctly. Therefore when lever is shifted forward or rear, machine starts rapidly moving.			
	get rusted. Therefore once joint gets lown even if a operator release a pedal, k.			

TYPE	COMMERCIAL NAME	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
M190	_	2002 ~ 2005	642
ZAF-M190T	_	2005 ~ 2006	178
M193	_	2003 ~ 2005	85
ZAF-M193T	_	2006 ~ 2010	171
ZAF-SM236	FB09H,FB10,FB14, FB15,FB15HB	2006 ~ 2010	837
ZAF-SM237	FB18,FB18HB,FB20A, FB20AHB	2007 ~ 2010	193
ZAF-M238	FB09ML,FB10ML,FB13ML	2006 ~ 2010	49
ZAF-M239	FB15ML	2007 ~ 2010	69
ZAF-SM243	FB15G,FB18G,FB20AG	2007 ~ 2010	9
ZAF-M254	FB25HB	2008 ~ 2010	10
M191	_	2004	1
M194	_	2004 ~ 2005	4
ZAF-M194T	_	2006 ~ 2010	3
M195	_	2004	1
ZAF-M195T	_	2007 ~ 2008	3
ZAF-M237	FB20A	2007	1
		TOTAL	2,256