

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2590	DATE	NOVEMBER 11,2010
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	THE RETAINING FORCE OF THE CRANKSHAFT OIL SEAL FITTED IN THE ENGINE FRONT CASE MAY HAVE BEEN DECREASED DUE TO THE MACHINING VARIABILITY OF THE FRONT CASE AND THE DEFORMATION BY THE EXCESSIVE PRESS FITTING FORCE OF THE OIL SEAL. BECAUSE OF THIS, THE SUBJECT OIL SEAL WOULD COME OUT AND THE ENGINE OIL WOULD BE LEAKED GRADUALLY CAUSING THE OIL PRESSURE WARNING LIGHT TO BE ILLUMINATED, AND IF USE CONTINUES UNDER THIS CONDITION, THE INNER PARTS OF THE ENGINE COULD BE SEIZED RESULTING IN THE VEHICLE UNABLE TO BE DRIVEN.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-H42A	MINICA	2004 TO 2005	6,258
GBD-H42V		2004 TO 2005	19,539
GBD-H47V		2004 TO 2005	1,633
CBA-H47A		2004 TO 2005	1,118
LA-H81W	eK-WAGON eK-SPORT eK-CLASSY eK-ACTIVE	2004	109
UA-H81W		2004	1,221
CBA-H81W		2004 TO 2005	43,365
DBA-H81W		2004 TO 2005	31,797
LE-U61T LE-U61TP	MINICAB	2003 TO 2004	8,083
LE-U62T LE-U62TP		2003 TO 2004	11,536
GBD-U61T GBD-U61TP		2004 TO 2005	8,768
GBD-U62T GBD-U62TP		2004 TO 2005	10,749
LE-U61V		2003 TO 2004	13,682
LE-U62V		2003 TO 2004	4,956
GBD-U61V		2004 TO 2005	12,306
GBD-U62V		2004 TO 2005	4,452
TA-U61W	TOWNBOX	2003 TO 2004	2,084
TA-U62W		2003 TO 2004	1,777
ABA-U62W		2004 TO 2005	1,103
CBA-U61W		2004 TO 2005	1,458
ABA-U61W		2004 TO 2005	472
CBA-U62W		2004 TO 2005	324

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
CBA-H91W	OTTI	2005	3,331	
DBA-H91W		2005	11,390	
LE-U71T LE-U71TP	CLIPPER	2003 TO 2004	4,935	
LE-U72T LE-U72TP		2003 TO 2004	5,385	
GBD-U71T GBD-U71TP		2004 TO 2005	4,404	
GBD-U72T GBD-U72TP		2004 TO 2005	4,455	
LE-U71V		2003 TO 2004	10,029	
LE-U72V		2003 TO 2004	4,261	
GBD-U71V		2004 TO 2005	9,199	
GBD-U72V		2004 TO 2005	3,484	
			TOTAL	247,663