

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2656	DATE	Nov.15 2010
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some large-sized intercity express buses, the amount of grease packed in the drive wheel bearings may be insufficient. If the vehicle continues to be used in this condition, insufficient lubrication of the bearings will occur. In the worst case, the vehicle becomes unable to drive or a fire could result.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-MU66JS	FUSO AERO KING	2008~2010	44
TOTAL			44