

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2661	DATE	Nov.19 2010
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some vehicles equipped with a mechanical automatic transmission, the length of the electrical wiring inside the valve body is improper. These wires may interfere with the clutch plate. If the vehicle continues to be used in this condition, the wiring may break. In the worst case, the vehicle will become unable to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-FBA20	FUSO CANTER	2010～2010	145
SKG-FBA30		2010～2010	8
SKG-FEB50		2010～2010	60
SKG-FEB90		2010	1
		TOTAL	214