

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	2658	DATE	November 25 ,2010
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	In the vehicles equipped with operation information systems, it has been found that there was a glitch in the body controller program and therefore, when engine stopped, the body controller data might be rewritten by the influence of the operation information systems. Thus, this may cause the hazard lamp, air conditioner fan, etc., controlled by the controller to malfunction.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
PDG-FRR34S2 PDG-FRR34T2	FORWARD	2008-2010	137	
PKG-FRR90S1 PKG-FRR90S2 PKG-FRR90T2		2008-2010	290	
PKG-FSR34S2 PKG-FSR34T2		2008-2010	24	
PKG-FSR90S2 PKG-FSR90T2		2008-2010	17	
PDG-FTR34S2 PDG-FTR34T2		2007-2010	85	
PDG-FVR34U2		2008-2010	3	
PDG-FVZ34U2		2008-2009	4	
BKG-NLR85AN BKG-NLR85N		ELF	2008-2010	5
BKG-NLS85AR			2009	1
BJG-NMR85AN BKG-NMR85AN BKG-NMR85N			2009-2010	22
BDG-NMS85AN			2010	1
BKG-NNR85AR	2009		1	
PDG-NPR75N PKG-NPR75N	2009-2010		40	
BDG-NPR85AN BDG-NPR85AR BKG-NPR85AN BKG-NPR85AR	2009-2010		36	
			TOTAL	666